



Vagues en ligne droite, sur la largeur	Lignes concaves dans la lamination	Traits diagonaux sur le pourtour	Vagues en angle sur un côté	<b>Problème</b>
Pression excessive du rouleau avant	Rouleaux d'alimentation déformés	Pression insuffisante, média trop épais	Pression insuffisante, rouleau latéral arrière droit ou gauche	<b>Cause</b>
Réduire pression du rouleau avant	Remplacer rouleaux	Resserrer le rouleau arrière	Resserrer le rouleau latéral arrière droit ou gauche	<b>Solution</b>



Angled waves on one side of the output.	Straight waves in the output.	Wake waves.	<b>Problem</b>
Insufficient rear left (or right) side roller pressure.	Excessive heat at the nip rollers.	Insufficient heat at the nip rollers.	<b>Cause</b>
Tighten the rear left (or right) side roller pressure.	Lower the roller temperature.	Raise the roller temperature.	<b>Solution</b>

Pour toute question, visitez notre site web: [www.southwestbusiness.ca](http://www.southwestbusiness.ca)  
ou appelez-nous sans frais: 1-877-285-7044

MIFL0129

HALIFAX NS  
902.477.0382

MONTREAL QC  
514.694.7741

OTTAWA ON  
613.744.7004

TORONTO ON  
416.285.7044

CALGARY AB  
403.717.1707

VANCOUVER BC  
604.574.9508