



Laminating Film Solutions



Straight wave lines across the output	Concave waves in the lamination	Angled waves on both sides of the output	Angled waves on one side of the output	Problem
Excessive front roller pressure	Feed rollers are warped	Insufficient pressure due to thick stock	Insufficient rear left (or right) side roller pressure	Cause
Loosen the front roller pressure	Replace rollers	Tighten the rear roller pressure	Tighten the rear left (or right) side roller pressure	Fix



Southwest Business has laminating systems for any job. From 13" to 65", 1 to 2 sided hot or cold films and mounting capabilities.

Southwest has the largest selection of stock and custom laminating films in the market.

Call us today for our latest price list.